


830

TUNING FORK
Certificate of Accuracy
March 31, 2017

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 229888 WAS TESTED
AND FOUND TO OSCILLATE AT 2614 CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 34.700 GHZ BAND TO
READ 25 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____




© 2002 4416

TUNING FORK
Certificate of Accuracy
March 31, 2017

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 335985 WAS TESTED
AND FOUND TO OSCILLATE AT 4169 CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 34.700 GHZ BAND TO
READ 40 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



© 2002 4416