

Blk Dodge
860


TUNING FORK
Certificate of Accuracy

March 31, 2017

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 155717 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 2618 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 34.700 _____ GHZ BAND TO
READ 25 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



© Goss 4518


TUNING FORK
Certificate of Accuracy

March 31, 2017

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 255187 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 4171 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 34.700 _____ GHZ BAND TO
READ 40 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



© Goss 4518