


813

TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 31, 2017
TUNING FORK SERIAL NUMBER 010147 WAS TESTED
AND FOUND TO OSCILLATE AT 1817 CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 24.150 GHZ BAND TO
READ 25 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____




© 2000 4418

TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 31, 2017
TUNING FORK SERIAL NUMBER 012409 WAS TESTED
AND FOUND TO OSCILLATE AT 2900 CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 24.150 GHZ BAND TO
READ 40 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



© 2000 4418