

874

TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 31, 2017
TUNING FORK SERIAL NUMBER 155718 WAS TESTED
AND FOUND TO OSCILLATE AT 2617 CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 34.700 GHZ BAND TO
READ 25 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004


SIGNED 

© Goss #18

TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 31, 2017
TUNING FORK SERIAL NUMBER 255188 WAS TESTED
AND FOUND TO OSCILLATE AT 4170 CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 34.700 GHZ BAND TO
READ 40 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED 

© Goss #18